

Report No



Auction Lot No
257

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
20/12/2022	Datsun 240Z	1972	815km	11243

Overall Rating	Comments
	Good project car

EXTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				
Glass		✓				Scratched in areas.
Bodywork	✓					Evidence of blisters in lower sections of bodywork.
Paintwork	✓					Recent closed door respray.
Lamps Condition			✓			L/H headlamp rusty. Other lamps in poor condition.
Bumper Bars						Front bar rusty. Rear bar tarnished and damaged.
Brightwork		✓				Aged.
Seals			✓			Poor, hatchback seal incorrect.
Convertible Roof					✓	

INTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Boot Area			✓			Tailgate has limited travel. Untidy and soiled.
Seats & Belts		✓				Aged.
Floor Coverings			✓			Torn and damaged U/S.
Headlining/Visors		✓				Rear interior lamp broken.
Trim			✓			Aged, generally untidy and damaged. Centre console cracked and loose.
Doors		✓				Door trims aged and damaged.
Windows and Mirrors		✓				Windows scratched.
Heating and Ventilation			✓			Temp lever not working and genarally poor.
Lights/Wipers/Washers/Horn			✓			Wipers N/W. High beam N/W.
Other Electrical				✓		
Entertainment Equipment			✓			No sound.
ABS/SRS					✓	

UNDERBODY

	Good	Fair	Repair	N/C	N/A	Comments
Structure			✓			Chassis rails and sills have advanced rust.
Corrosion			✓			Floors have advanced rust and evidence of substantial welding and plating repairs.
Powertrain	✓		✓			Clutch slave leaking and hose perished.
Exhaust		✓				
Brakes	✓					
Wheels & Tyres		✓				Wheels tarnished and tyres rubbing.
Steering & Suspension		✓				Aged but servicable.
Fuel System		✓				Fuel tank badly dented.
Fluid Leaks	✓					

ENGINE BAY

	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				Over spray.
Fluid Levels/Condition			✓			Engine oil level overfull.

Cooling System	✓					
Power Steering					✓	
Electrical	✓					
Engine Running			✓			Not running on all cylinders.
Air Conditioning					✓	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance			✓			Not running well.
Transmission	✓					
Noise and Vibration	✓					
Steering and Suspension	✓					
Braking	✓					
Clutch	✓					
Instruments			✓			Fuel gauge needle bent, gauge glass detached and ill fitted. Clock N/W.

General Comments

Key					
Good	Operational or well presented at time of inspection				U/S Unservicable
Fair	Commensurate for age of vehicle but has wear and tear				N/S Not secure
Repair	Requires repair, replacement or refurbishment				N/W Not working
Wetting	Fluid escaping with the potential to drip				N/A Not Applicable
Leaking	Fluid escaping and dripping				N/C Not checked
★ ☆ ☆ ☆ ☆	Vehicle requires substantial work or restoration				
★ ★ ☆ ☆ ☆	Vehicle is in poor condition and in need of TLC				
★ ★ ★ ☆ ☆	Vehicle is commensurate with age and useable				
★ ★ ★ ★ ☆	Vehicle is in very good condition				
★ ★ ★ ★ ★	Vehicle is in excellent condition				

Disclaimer

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.

This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.

Pge 2/2